

## Geeetech A30 3D Printer Package List

NO.	Name	Description	Qty	Check
<b>Materials in the Foam box</b>				
1	Bottom frame parts	Pre-assembled	1	<input type="checkbox"/>
2	Vertical frame parts	Pre-assembled	1	<input type="checkbox"/>
3	Control box	12V, 41A, 500W	1	<input type="checkbox"/>
<b>Materials in the Tool box</b>				
4	Hex screw	M5*20mm	4	<input type="checkbox"/>
5	Spring washer	M5	4	<input type="checkbox"/>
6	Filament spool		1	<input type="checkbox"/>
7	Hex screw	M3*6mm	2	<input type="checkbox"/>
8	Power cable		1	<input type="checkbox"/>
9	A-B USB cord	Blue	1	<input type="checkbox"/>
10	Z axis stator kit	Aluminium alloy	2	<input type="checkbox"/>
11	3D touch stator	Thickness 5mm	1	<input type="checkbox"/>
12	Filament detector kit		1	<input type="checkbox"/>
13	zip tie		1bunch	<input type="checkbox"/>
14	Allen key		1	<input type="checkbox"/>
15	Pin		1	<input type="checkbox"/>
16	Starter filament		1	<input type="checkbox"/>
17	Spare screw package		1	<input type="checkbox"/>
18	TF card	1GB	1	<input type="checkbox"/>
		Reviewer		